



HITANO ENTERPRISE CORP.

TEL : 886-2-2299-1331 FAX : 886-2-2298-2466



7F-7, NO.3, WU-CHUAN 1ST RD., NEW TAIPEI INDUSTRIAL PARK, NEW TAIPEI CITY, TAIWAN R.O.C.

<http://www.hitano.com.tw> E-mail:info@hitano.com.tw

Updated Storage Conditions for HITANO MLCC and CHIP RESISTOR

Dear valuable customers,

This letter is writing to you about the update storage condition of the HITANO multilayer ceramic capacitors and chip resistor.

To provide clear understanding of the storage conditions and lifespan limitations of multilayer ceramic capacitors and chip resistor, our Quality Assurance Department has revised and updated the relevant documentation.

It is important to note that multilayer ceramic capacitors and chip resistors, when stored for extended periods without proper environmental control, may experience changes that affect their solderability and electrical performance.

To address this, HITANO provides comprehensive reference guidelines covering recommended storage conditions and duration, enabling customers to evaluate the reliability of their inventory based on their specific warehouse environment and timeframe, thereby ensuring that components maintain optimal quality.

Please review and follow the updated guidelines to ensure product quality and reliability.

Yours Sincerely

For and on behalf of
HITANO ENTERPRISE CORP.

Authorized Signature

HITANO ENTERPRISE CORP.